

## TOP 10 SUPPLY CHAIN PRACTICES

**01** Ensure greater traceability in the supply chain.

**02** Foster greater cooperation, coordination, and accountability among all participants.

**03**

Increase information sharing to strengthen supply chain integrity.

84%

8%

**04**

Include provisions in supplier contracts that facilitate and improve oversight.



**05**

Calibrate supplier assessments according to the risk level.



**06**

Engage proactively with suppliers on an ongoing basis.



**07**

Ensure that supplier requirements flow down to subcontractors.



**08**

Develop procedures for reporting on and ensuring destruction of counterfeit parts.



**09**

Work collaboratively with government authorities to support product safety and quality.



**10**

Increase awareness among consumers and end users about the hazards of counterfeits.

